

Document Number: 80029631

Document Version: A

Printed or electronic versions of this document not accessed directly from the designated Hillrom Controlled Quality Information System are For Reference Only.

Customer Service Bulletin

Product:	Product Configuration Tool		
Subject:	Software Release Notes for version 1.9.3		
HW Version(s) Affected:	N/A	SW Version(s) Affected:	All
Serial Numbers Affected:	N/A	Lot or Date Code Affected:	N/A

Classification:	Next Visi	t		
Distribution:	⊠ Customer Care		☑ Product Service	⊠ Field Service
	\boxtimes ASPs	□ Distributors	⊠ Customers	\square Company Confidential
Summary:				

The Configuration Tool has been updated to version 1.93 from the previous version 1.92 to address a security vulnerability with the share file feature.

Action Needed:

Effective Immediately, as a precautionary measure we recommend all users immediately change their password for the Configuration Tool.

How to change your password:

- 1) Open a browser and go to the site https://config.welchallyn.com/configurator/
- 2) Click on Forgot your password? Reset it here!
- 3) Enter your Email Address and then click CONTINUE.
- 4) Answer the security question that you chose during registration.
- 5) Enter a new password and confirm the password and then click SUBMIT.

END OF BULLETIN

THIS INFORMATION IS THE PROPERTY OF HILLROM HOLDINGS AND AS SUCH SHALL NOT BE REPRODUCED, COPIED, OR USED AS A BASIS FOR THE MANUFACTURE OR SALE OF EQUIPMENT, DEVICES, OR SOFTWARE WITHOUT THE EXPRESS WRITTEN PERMISSION OF HILLROM.				
80026075 Rev A. Parent: WI-17206803	80026075A TSB-CSB TEMPLATE FLC.DOCM	1		



Document Number: 80029631

Document Version: A

Version	Sec, Pg, Para Changed	Change Made	Date Version Created	Version Created By (initials)
Α	N/A	Initial Release	2022-02-23	KMG