

Question or Item	Answer
Did you verify that you are using the most recent version of this form?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Date	01AUG2023
Individual creating the TSB	Matthew Bell
Product(s) affected:	CSM
Model(s) affected:	All CSM models except those sold into China
Lot or Date Code Affected:	Product manufactured after 2023-08-01

NOTE: China and devices sold into China are exempt from this Customer Service Bulletin.


Subject:

A new power supply has been introduced to the CSM device (models noted above), 7000-PS Replacement Power Supply Service Kit, and Service Loaner Devices effective 2023-08-01.

This change only impacts appearance. There is no change in customer facing part numbers, color, electrical specifications, or compatible mounting options.

To mount this new power supply to mobile stands released prior to September 2022 (MM 413165), a mounting bracket is needed. The mounting bracket is kitted with every new power supply including the 7000-PS replacement. Please see the assembly instructions kitted with each device for details on how to mount the power supply to the stand.

Details: The new power supply has a slightly different appearance. See photos below



Action: No action needed. This bulletin is intended for clarification only. The new power supply is functionally identical to the existing supply and is backwards compatible with all intended CSM devices and approved mounting solutions in service centers and the field.

This change does not drive a requirement to replace existing power supplies kitted with devices received for service.



Version	Sec, Pg, Para Changed	Change Made	Date Version Created	Version Created By (initials)
A	N/A	Initial Release	2023-03-08	BWH
B	Details:	Replaced images	2023-08-01	MDB