

To: SureSight Customers

From: Melissa Stancato

Re: SureSight Vision Screener End of Life

Date: December 10, 2020

Dear SureSight Customer,

Effective April 1, 2021 WelchAllyn SureSight vision screener will have reached End of Service Life (EoSL) and will no longer be serviced or calibrated. If you would like a final calibration of your device, please contact your service team to schedule an RMA prior to April 1, 2021.

For reference, below is a detailed list of part numbers and their recommended replacements.

Discontinued Part Number	Description	Replacement Part Number	Description
14010	SURESIGHT AUTOREFRCTOR	VS100S-B	SPOT VISION SCREENER, PLUGB/US
14012	SURESIGHT AUTOREFACTOR (EUR)	VS100S-2	SPOT VISION SCREENER, PLUG2/EUR
14014	SURESIGHT, AUTOREFRACTOR (UK)	VS100S-4	SPOT VISION SCREENER, PLUG4/UK
14016	SURESIGHT AUTOREFRACTOR (AUST)	VS100S-66	SPOT VISION SCREENER, PLUG66/AUS
14000	SURESIGHT,VISION SCREENER	VS100S-B	SPOT VISION SCREENER, PLUG B/US
14002	SURESIGHT,VISION SCREENER(EUR)	VS100S-2	SPOT VISION SCREENER, PLUG 2/EUR
14004	SURESIGHT VISION SCREENER (UK)	VS100S-4	SPOT VISION SCREENER, PLUG4/UK
14006	SURESIGHT VISION SCR (AUST)	VS100S-66	SPOT VISION SCREENER, PLUG 66/AUS

Should you have any questions regarding this notification, please do not hesitate to contact Hillrom Customer Care.

Regards,

**Melissa Stancato**

Senior Product Manager

Vision Screening & Diagnostics