

May 23, 2023

Dear Valued Customer,

This letter is to inform you that effective October 1, 2023, Baxter will discontinue all technical phone support, repair and service, calibration, and parts support activities for the Welch Allyn® Propaq® LT Monitor. As a reminder, on October 1, 2018 we ended manufacturing of the Propaq LT Monitor globally.

A selection of the impacted part numbers is attached in Appendix A of this letter.

Baxter offers a broad portfolio of patient monitoring devices suitable for replacing the Propaq LT Monitor based on your use case. To obtain more information about replacement options or to create a transition plan for your facility, please contact your local Baxter sales representative or customer care for additional details.

We thank you for your business, partnership, and loyalty, and we look forward to continuing to serve your needs with other Baxter products. Please contact our customer service department at 1-800-535-6663 or your Baxter representative with questions regarding this notice.

Sincerely,



James Bennett  
Associate Marketing Manager, Global Marketing  
Patient Monitoring  
Baxter

**APPENDIX A**

802LT0N-0E0	802LT0S-0E0T	802LT0N-0E6	802LTRN-0L2	802LTRS-L
802LT0N-CL2-FR	802LT0S-CL2-EN	802LTAN-UE1	802LTRN-CE6	802LTAN-0L0
802LT0N-UE4	802LT0S-UE6	802LTAS-CL6	802LTRS-CE1	802LTAN-UL6
802LT0S-CE2	802LT0N-CL1	802LTRN-0E6	802LT0N-UL0	802LTAS-UL2-SP
802LT0S-CL2-PO	802LT0N-CL6	802LTRN-UL4A	802LTAN-UL2-GE	802LTRN-UE2
802LT0N-0E0M	802LT0S-0L0	802LT0N-0L0-L	802LTAS-UL2	802LTRS-UE1
802LT0N-CL2-GE	802LT0S-CL2-FR	802LTAN-UE1A	802LTRN-CL0	802LTAN-CE1
802LT0N-UE6	802LT0S-UE8	802LTAS-L	802LTRS-CE2	802LTAS-0E0
802LT0S-CE4	802LT0N-CL2	802LTRN-0L0	802LT0S-0E0-L	802LTAS-UL2-SW
802LT0S-CL2-SP	802LT0N-UE1	802LTRN-UL6	802LTAN-UL2-IT	802LTRN-UE2A
802LT0N-0E0R	802LT0S-0L0R	802LT0N-0L1	802LTAS-UL2-DU	802LTRS-UE1A
802LT0N-CL2-IT	802LT0S-CL2-GE	802LTAN-UE2	802LTRN-CL2	802LTAN-CE2
802LT0N-UL1	802LT0S-UL2	802LTAS-UE1	802LTRS-CE4	802LTAS-UL1
802LT0S-UL1	802LT0N-CL2-DU	802LTRN-0L0-L	802LT0S-0L0-L	802LTAS-UL4
802LT0S-CL2-SW	802LT0N-UE1M	802LTRN-UL6A	802LTAN-UL2-PL	802LTRN-UE4
802LT0N-0L0	802LT0S-0L0T	802LT0N-0L2	802LTAS-UL2-EN	802LTRS-UE2
802LT0N-CL2-PL	802LT0S-CL2-IT	802LTAN-UE6	802LTRN-CL4	802LTAN-CE4
802LT0N-UL2	802LT0S-UL4	802LTAS-UE1A	802LTRS-CE6	802LTAS-CE1
802LT0S-CE6	802LT0N-CL2-EN	802LTRN-0L0R	802LT0S-CL0	802LTAS-UL6
802LT0S-CL4	802LT0N-UE2	802LTRS-0E0	802LTAN-UL2-PO	802LTRN-UE4A
802LT0N-0L0R	802LT0S-CE1	802LT0N-0L4	802LTAS-UL2-FR	802LTRS-UE4
802LT0N-CL2-PO	802LT0S-CL2-PL	802LTAN-UL1	802LTRN-CL6	802LTAN-CE6
802LT0N-UL4	802LT0S-UL6	802LTAS-UE2	802LTRS-CL0	802LTAS-CE2
802LT0S-CE8	802LTRS-0E0T	802LTRN-0L4	802LT0S-CL6	802LTRN-0E0
802LT0S-CL4-EN	802LTRN-0L0T	802LTRS-0E0-L	802LTAN-UL2-SP	802LTRN-UE6
802LT0N-0L0T	802LTRN-0E0C	802LT0N-0L6	802LTAS-UL2-GE	802LTRS-UE6
802LT0N-CL2-SP	802LTAS-UL4-EN	802LTAN-UL2	802LTRN-L	802LTAN-CL1
802LT0N-UL6	802LT0N-0E1	802LTAS-UE4	802LTRS-CL2	802LTAS-CE4
802LT0S-CL1	802LTAN-CL6	802LTRN-0L6	802LT0S-L	802LTRN-0E0-L
802LT0S-UE1	802LTAS-CL1	802LTRS-0E0R	802LTAN-UL2-SW	802LTRN-UE6A
802LT0N-CE1	802LTRN-0E1	802LT0N-CL0	802LTAS-UL2-IT	802LTRS-UE6A
802LT0N-CL2-SW	802LTRN-UL2	802LTAN-UL2-DU	802LTRN-UE1	802LTAN-CL2
802LT0S-0E0	802LT0N-0E2	802LTAS-UE6	802LTRS-CL4	802LTAS-CE6
802LT0S-CL2	802LTAN-L	802LTRN-CE1	802LT0S-UL0	802LTRN-0E0R
802LT0S-UE2	802LTAS-CL2	802LTRS-UL0	802LTAN-UL4	802LTRN-UL0
802LT0N-CE4	802LTRN-0E2	802LT0N-L	802LTAS-UL2-PL	802LTRS-UL0A
802LT0N-CL4	802LTRN-UL2A	802LTAN-UL2-EN	802LTRN-UE1A	802LTAN-CL4
802LT0S-0E0R	802LT0N-0E4	802LTAS-UE8	802LTRS-CL6	802LTAS-CE8
802LT0S-CL2-DU	802LTAS-0L0	802LTRN-CE2	802LTAN-0E0	802LTRN-0E0T
802LT0S-UE4	802LTAS-CL4	802LTRS-0L0R	802LTAN-UL4-EN	802LTRN-UL0A
802LT0N-CE6	802LTRN-0E4	802LT0N-UE0M	802LTAS-UL2-PO	802LTRS-UL2
802LT0N-CL4-EN	802LTRN-UL4	802LTAN-UL2-FR	802LTRS-0L0	802LTRS-UL2A
802LTRS-UL6	802LTRS-UL4A	802LTRS-UL4	802LT0N-CE1	802LT0N-0E0
802LT0N-UE1	802LT0S-UE1	802LT0S-CE1	802LT0N-UL1	802LT0N-UE1M
			802LT0S-0E0	802LT0S-UL1