

April 15, 2021

Dear Valued Customer,

We are issuing this letter to inform you that due to low sales volume, effective October 1, 2021, Hillrom will discontinue the sale and manufacture of the Qtel v5.0.1 as well as the S2 transmitter.

Hillrom will continue to provide depot repair, technical services including phone support and parts support activities on the product addressed in this notification, for up to 5 years or until parts are no longer available.

A selection of the impacted part numbers is below

Part number	Description
11089-009-60	SOFTWARE Q-TEL v5.0.1 WORKSTATION
11089-009-61	SOFTWARE Q-TEL v5.0.1 WORKSTATION 64BIT
11089-009-70	Software Q-tel v5.0.1 Q-progress
76210-001-50	S2 TRANSMITTER 5 WIRE ECG AND SPO2

We thank you for your business, partnership and loyalty, and we look forward to continuing to serve your needs with other Hillrom[™] products. Please contact our customer service department or your Hillrom representative with questions regarding this notice.

Sincerely,

Lillian V. O'Neill Product Specialist, Global Marketing Diagnostic Cardiology Hillrom

4341 State Street Road Skaneateles, NY 13153 800.535.6663