

May 23, 2023

Dear Valued Customer.

This letter is to inform you that effective June 30, 2023, Baxter will discontinue all technical phone support, repair and service, calibration, and parts support activities associated with our Welch Allyn® Spot Vital Signs® LXi Device. As a reminder, on November 30, 2017 we ended manufacturing of the Spot Vital Signs LXi.

A selection of the impacted part numbers is attached in Appendix A of this letter.

Baxter recommends the Welch Allyn® Spot Vital Signs® 4400 Device or the Welch Allyn® Connex® Spot Monitor Device as a replacement vital signs device for your Spot Vital Signs LXi Device, depending on your use case and what devices are available in your region. Features of the Spot 4400 include:

- Measure blood pressure in just 15 seconds with SureBP® technology
- BP averaging to help ensure accurate hypertension detection and diagnosis
- SureTemp® Plus Oral / Axillary Thermometry
- Option for Nonin® SpO2 technology
- 7" color touchscreen for a simplified workflow
- Options for documenting patient observations (i.e. Respiration Rate, BMI)
- EMR connectivity to help minimize documentation errors



Features of the Connex Spot Monitor include:

- Measure blood pressure in just 15 seconds with SureBP® technology
- BP averaging to help ensure accurate hypertension detection and diagnosis
- Choose between SureTemp® Plus or Braun ThermoScan® PRO 6000 Thermometry
- Options for Masimo®, Nellcor®, and Nonin® SpO2 technology
- Customize workflows to document patient observations and vitals modifiers
- Help identify signs of patient deterioration with automated Early Warning Scores
- EMR connectivity to help minimize documentation errors

To obtain more information about the Welch Allyn Spot Vital Signs 4400 Device or the Welch Allyn Connex Spot Monitor Device as replacement options from Baxter or to create a transition plan for your facility, please contact your local Baxter sales representative or customer care for additional details.

We thank you for your business, partnership, and loyalty, and we look forward to continuing to serve your needs with other Baxter products. Please contact our customer service department at 1-800-535-6663 or your Baxter representative with questions regarding this notice.

Sincerely,

James Bennett

Associate Marketing Manager, Global Marketing

Patient Monitorina

Baxter



APPENDIX A

45MT0-F1	45NT0-EX	450T0-P2	450T0-E4	45ME0-SW2	45NE0-EX	45ME0-I2
45MT0-F2	45MT0-E1	45NT0-E1R	450T0-SW2	45NE0-E6	45NE0-DN2	45ME0-E1R
45MT0-SW2	45MT0-I2	45MT0-E2	45MT0-E6-EC2	45NE0-S1	45NE0-F2	45NE0-E1G
45NT0-E6	45NT0-DT2	45MT0-P2	450T0-E6	450E0-E6	450E0-DN2	45NE0-I2
450T0-E2	45NT0-F2	45NT0-E1T	45NT0-E1-RNTL	450E0-SW2	450E0-F2	450E0-E1G
450T0-F1	450T0-E1	45NT0-I2	45MT0-E1-RNTL	45ME0-EC2	45ME0-DT2	450E0-I2
450T0-EX	450T0-I2	45NT0-S2	45ME0-S1	450E0-E2-L	45ME0-FN2	45ME0-E1T
45MT0-DN2	450T0-E6-EC2	450T0-S1	45NE0-E2	45MEO-E2-L	45ME0-EX	45ME0-L
45MT0-FN2	45MT0-E1G	450T0-E1R	45NE0-N2	45NE0-E6-L	45NE0-DT2	45NE0-E1R
45NT0-DN2	45MT0-L	45MT0-E4	450E0-N2	45NE0-S2	45NE0-FN2	45NE0-E1T
45NT0-S1	45NT0-E1	45MT0-S1	450E0-S1	450E0-EC2	450E0-DT2	45NE0-L
450T0-DN2	45NT0-FN2	45NT0-E2	45ME0-E6	45ME0-E4	450E0-FN2	450E0-E2
450T0-F2	450T0-E1G	45NT0-L	45ME0-P2	45ME0-F1	45ME0-E1	450E0-P2
45MT0-EX	450T0-N2	45NT0-SW2	45ME0-S2	45ME0-E2-L	45ME0-G2	45ME0-E2
45MT0-DT2	45NT0-E6-EC2	450T0-S2	45NE0-E4	45NE0-EC2	450E0-EX	45ME0-N2
45MT0-G2	45MT0-E1T	45MT0-E1R	45NE0-P2	45NE0-F1	45NE0-E1	450E0-E1R
450T0-G2	45MT0-N2	45MT0-E6	450E0-E4	45NE0-SW2	45NE0-G2	4500-922
45NT0-F1	45NT0-E1G	45MT0-S2	450E0-S2	450E0-F1	450E0-E1	4500-920
450T0-DT2	45NT0-G2	45NT0-E4	45ME0-E6-L	45ME0-DN2	450E0-G2	45ME0-E6-EC2
450T0-FN2	45NT0-P2	45NT0-N2	45NE0-E2-L	45ME0-F2	45ME0-E1G	450E0-E6-EC2
						45NE0-E6-EC2